

SL SHOP (Sales & Service) Ltd

Vehicle Health Check

CUSTOMER DETAIL

Mr Tim Alan Hunt
 H 01932 784086
 Tel M 07711 640 153
 W

VEHICLE DETAIL

Make Mercedes-Benz
 Model 280 SL
 Registration HEX390Y
 Chassis No WDB10704222013716
 Mileage 62615

VHC NO

10541

Date 2023-08-25
 Service Advisor Tom Sansom
 MOT Due 26/09/2023
 Inspected By m - Stefan Rich

Comments / Recommendations

Initial Road Test 00IRT

G	Engine performance / smoke / noises	
G	Brake performance / spongy / pulling left or right	
A	Steering in straight position / feel / noises	Steering alignment slightly out to the right.
G	Check operation of warning lights 54585	
A	Check operation of wipers and washers 86000	1 of the wiper blades is splitting.
G	Check operation of horn 54105	
G	Check operation of parking brake 42120	

lights 82000

A	Check operation of front external lights 82195	NSF fog light inoperative.
G	Check operation of rear external lights 82225	

Interior 91000

G	Check seat and seat belt operation 91090	
G	Check interior lights 82165	
G	Heater motor operation 83135	
G	Radio and aerial operation 82345	

Engine Bay 18000

A	Antifreeze strength 50000	Antifreeze is week, suggest a coolant flush, vehicle would benefit from a radiator refurbishment.
G	Remove heater box lid-check bulkhead 62015	
A	Check battery condition 54080	Battery clamp is missing.
G	Check charging Volts 15030	13v
G	Check G/Box oil level 18000	
G	Check engine oil level / condition 18000	
G	Check for fuel leaks 07075	
G	Check brake fluid level / condition 42000	

Under Vehicle 00UV

G	Check drop links 32060	
G	Check front wishbones 33030	
G	Check shock absorbers 32000	
G	Check engine mountings 22010	
G	Check subframe bushes 33010	
G	Check for general oil leaks 18000	
G	Check propshaft couplings condition 41015	

SL SHOP (Sales & Service) Ltd

Vehicle Health Check

CUSTOMER DETAIL

Mr Tim Alan Hunt
 H 01932 784086
 Tel M 07711 640 153
 W

VEHICLE DETAIL

Make Mercedes-Benz
 Model 280 SL
 Registration HEX390Y
 Chassis No WDB10704222013716
 Mileage 62615

VHC NO

10541

Date 2023-08-25
 Service Advisor Tom Sansom
 MOT Due 26/09/2023
 Inspected By m - Stefan Rich

Comments / Recommendations

G	Check fuel pump pipes/filter package 47045	
A	Check exhaust system condition 14060	Downpipe is corroded would benefit from replacing.
G	General underbody corrosion / Waxoyl 61000	
G	Visual check on brake pads and discs 42000	
G	Check rear drive shafts/boots 35030	

Soft Top Check 77000

A	Check soft top open/closure/catch mechanism 7700	Deck seal is split and not water tight suggest replacing.
----------	--	---

Water Test 00WT

G	Check bulkhead for leaks	
G	Check window/door seals for leaks	
G	Check boot/rear lights for leaks	
A	Hardtop water leaks	Hardtop rear screen bonding has failed resulting in water ingress. Suggest removing glass cleaning old adhesive and re bonding to Hardtop

Tyres Tread (mm) Manufacturer Size Comments/Recommendations

Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front	8.0			
G N/S Rear	9.0			
G O/S Front	8.0			
G O/S Rear	9.0			
G Spare	7.0			

Brakes Drums Pads Discs Comments/Recommendations

	Drums	Pads		Discs		Comments/Recommendations
			% Remaining		% Remaining	
N/S Front	N	G	95	G	95	
N/S Rear	N	G	90	G	90	
O/S Front	N	G	95	G	95	
O/S Rear	N	G	90	G	90	

Photos

Customer Signature _____ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.